## JOINT PHOTOGRAPHIC INTELLIGENCE BRIEF

## ARMY-NAVY-CIA

(Published and Disseminated by CIA/PIC)

SUBJECT: Similarity of Probable Assembly and

1. m 31. 99

25X9

25X9

Checkout buildings at Semipalatinsk

Airfield and Kapustin Yar/Vladimi-

rovka Missile Test Center


NO : PIC/JB-9/60 DATE: 26 January 1960

PHOTO DATA:		2
	<u> </u>	
MAP DATA:		
US Air Target Chart S	eries 200 - 0239 - 11A Dec 58 (Semipalatinsk A/	F)
	200 - 0235 - 22A Feb 59 (KYVMTC)	•
REMARKS:		
Analysis conducted in	an effort to determine the existing relationship	
	missile-related installations has revealed	d
and three buildings located	en two buildings located at Semipalatinsk Airfield at the Kapustin Yar/Vladimirovka Missile Test	
Center. All of these building	ngs were present on photography.	2
These buildings are la	rge rectangular, drive-through structures with	
nigh center sections betwee	en single-story monitor-roofed end sections I are	зe
illustrated on the following	xtend up into the monitors. A typical building is page.	
:.		
	One of the	
two buildings was apparentl	ly being utilized as a drive-in rather than a drive-	**
through building when photo	graphed on see JR-2/58). The	

Approved For Release 2005/12 TOP SECRET 25X1D

25X1

PIC/JB-9/60



The dimensions shown represent the range of measurements obtained for the five buildings. Since the degree of difference is so small, it is probable that all five buildings are actually the same size.

25X1D

25X1D

At Kapustin Yar, one of the buildings is found at the SAM area while the other two are found at one of the SSM areas (areas 3-A and 3-D USATC 0235-22A). The building located in the SAM area (area 3-A) is centrally situated in a heavily-secured area which also contains four smaller structures and a storage bunker adjacent to a large unoccupied revetted hardstand.

The other two buildings, complete in are located at 25X	(1E
48°36'N/46°13'E, within an SSM launch complex (area 3D). These buildings	
are located within two individually-secured areas served by a common road.	
One of the areas also contains a storage bunker and four buildings, one of which	
was under construction in The second area contains a possible	
buried tank or bunker and two small buildings in addition to the drive-through structure.	

Analysis of photography has resulted in the identification of area 3D as an SSM complex, rather than a SAM complex as indicated on the referenced chart.

- 2. -

Approved For Release 2005/12/25 : CIA-RDP78T04751A000300050010-7

TOP SECRET